



For maximum glow longevity, follow the washing and care instructions below for all projects stitched/embroidered with these threads. Note that after 50 washings, a decrease of glow effect may be observed.

Washing:

Cool water only with the maximum temperature at 40 ° C/104 ° F.

Drying:

Machine dry at around 60 ° C/140 ° F; remember not to reach 80 ° C/176 ° F.

Ironing:

110 ° C/230 ° F is fine, but AVOID STEAM.

Dry Cleaning:

Yes, but ONLY with Petroleum-based or Perchloroethylene-based detergents.

NO Hot Temperature (wet heat) over 80 ° C/176 ° F, like hot water or steam ironing.

NO Bleaching

NO Chlorine-based Detergents